



## Post-Event Assessment





Typical nearshore seagrass



Typical seagrass drop off





Typical dense seagrass area

File: CLI-2014-0124 Location: Marine Stadium Project Manager: Lourdes Barrelli

Date: 3-24-2016

## Post-Event Assessment





Linear Feet East of Marine Stadium

